

Inspection Photos
Operator: Simcoe
API: 007-06320
Date: 12/13/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the eastern project area from the southeastern corner facing northward. Revegetation is progressing with western wheatgrass, crested wheatgrass, and sand dropseed.



Photo 3. View of dense kochia debris within the northwestern project area.



Photo 4. View of reference area comprised irrigated grass field. Vegetation is largely dormant and mowed at this time.