

Inspection Photos
Operator: Morningstar
API: 007-06196
Date: 12/13/2021



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is progressing with Indian ricegrass, crested wheatgrass, and rubber rabbitbrush. Pinyon and juniper trees growing along the edges of the project area.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of sagebrush, Indian ricegrass, blue grama, James galleta, and cholla.