

Inspection Photos  
Operator: Morningstar  
API: 007-06222  
Date: 12/13/2021



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with Indian ricegrass, crested wheatgrass, western wheatgrass, and rubber rabbitbrush. Pinyon and juniper trees growing along the edges of the project area.





Photo 3. View of the eastern project area from the southeastern corner facing northward.





Photo 4. View of reference area comprised of pinyon and juniper woodland with understory of sagebrush, Indian ricegrass, blue grama, James galleta, and cholla.