

**Inspection Photos**  
**Operator: Morningstar**  
**API: 007-06183**  
**Date: 12/13/2021**



Photo 1. View of the project area from the eastern entrance, facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing with Indian ricegrass, crested wheatgrass, western wheatgrass, and rubber rabbitbrush. Pinyon and juniper trees growing along the edges of the project area.



Photo 3. View of the eastern project area from the northeastern corner facing southward.



Photo 4. View of Russian thistle debris within the northeastern project area, needs to be removed and properly disposed of.



Photo 5. View of reference area comprised of pinyon and juniper woodland with understory of sagebrush, Indian ricegrass, blue grama, James galleta, and cholla.