

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/14/2021

Submitted Date:

12/14/2021

Document Number:

696303849

FIELD INSPECTION FORM

Loc ID 421208 Inspector Name: PETRIE, ERICA On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 8960
Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY
Address: 410 17TH STREET SUITE #1400
City: DENVER State: CO Zip: 80202

Findings:

- 19 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
		EHSRC@bonanzacrk.com	All Inspections
Pesicka, Conor		conor.pesicka@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
421203	WELL	PR	08/01/2021	GW	123-32841	Antelope S-31	PR
421303	WELL	TA	10/05/2020	GW	123-32876	Antelope 24-31	TA
421308	WELL	SI	08/01/2021	GW	123-32878	Antelope 13-31	SI
421309	WELL	PR	08/01/2021	GW	123-32879	Antelope 23-31	PR
421313	WELL	TA	10/05/2020	GW	123-32882	Antelope 34-31	TA
421320	WELL	TA	04/25/2019	GW	123-32885	Antelope 33-31	TA
421331	WELL	TA	10/07/2019	GW	123-32889	Antelope 43-31	TA
421332	WELL	TA	10/07/2019	GW	123-32890	Antelope 44-31	TA

General Comment:

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:			Date:

Emergency Contact Number:

Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unmarked Risers at Tanks and Wellheads; see photos		
Corrective Action:	Comply with Rule 606		Date: <u>12/17/2021</u>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	Panels		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:			Date:

Equipment:

Type: Gas Meter Run	# 3		corrective date
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 7		
Comment:	Appear to be plumbed to surface		
Corrective Action:			Date:

Type: Plunger Lift	# 3		
Comment:			
Corrective Action:			Date:
Type: Other	# 4		
Comment:	TA Wellheads		
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 3		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	OTHER	BV CONCRETE		
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 BBLS	
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:	Shares berm with Crude Oil Tanks			
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLS	STEEL AST		40.352970,-104.361680
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				

Corrective Action:		Date:	
--------------------	--	-------	--

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 421203 Type: WELL API Number: 123-32841 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

Facility ID: 421303 Type: WELL API Number: 123-32876 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment: TA MIT: 09.30.2020
 Corrective Action: _____ Date: _____

Facility ID: 421308 Type: WELL API Number: 123-32878 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment: SI - This Well is on another PAD - Antelope G-31 PAD Location ID - 421200
 Corrective Action: _____ Date: _____

Facility ID: 421309 Type: WELL API Number: 123-32879 Status: PR Insp. Status: PR

Producing Well

Comment: PR
 Corrective Action: _____ Date: _____

Facility ID: 421313 Type: WELL API Number: 123-32882 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment: TA - MIT: 09.30.2020
 Corrective Action: _____ Date: _____

Facility ID: 421320 Type: WELL API Number: 123-32885 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____
 Comment: TA - MIT: 04.09.2021
 Corrective Action: _____ Date: _____

Facility ID: 421331 Type: WELL API Number: 123-32889 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Facility ID: 421332 Type: WELL API Number: 123-32890 Status: TA Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
Routine Field Inspection. Unmarked Risers at Tanks and Wellheads.	petrie	12/14/2021

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696303850	Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5607711