

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/13/2021

Submitted Date:

12/15/2021

Document Number:

701102334**FIELD INSPECTION FORM**Loc ID 336552 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 16700Name of Operator: CHEVRON USA INCAddress: 100 CHEVRON ROADCity: RANGELY State: CO Zip: 81648**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name        | Phone          | Email                       | Comment                         |
|---------------------|----------------|-----------------------------|---------------------------------|
| Regulatory, Rangely |                | RangelyRegulatr@scoutep.com | <a href="#">All Inspections</a> |
| Sanford, Anita      | (970) 675-3842 | Anita.Sanford@scoutep.com   | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name       | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------|-------------|
| 231527      | WELL | PR     | 07/01/2021  | OW         | 103-09198 | COLTHARP, W.H. C 2X | PR          |

**General Comment:**[COGCC Routine Inspection](#)

**Location****Lease Road:**

|                   |        |       |  |
|-------------------|--------|-------|--|
| Type              | Access |       |  |
| comment:          |        |       |  |
| Corrective Action |        | Date: |  |

Overall Good: ☒**Signs/Marker:**

|                    |          |       |  |
|--------------------|----------|-------|--|
| Type               | WELLHEAD |       |  |
| Comment:           |          |       |  |
| Corrective Action: |          | Date: |  |

**Emergency Contact Number:**

|                    |     |       |  |
|--------------------|-----|-------|--|
| Comment:           | 911 |       |  |
| Corrective Action: |     | Date: |  |

**Good Housekeeping:**

|                    |       |       |  |
|--------------------|-------|-------|--|
| Type               | TRASH |       |  |
| Comment:           |       |       |  |
| Corrective Action: |       | Date: |  |

Overall Good: ☒**Spills:**

| Type | Area | Volume |  |  |
|------|------|--------|--|--|
|------|------|--------|--|--|

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

|                    |           |       |  |
|--------------------|-----------|-------|--|
| Type               | WELLHEAD  |       |  |
| Comment:           |           |       |  |
| Corrective Action: |           | Date: |  |
| Type               | PUMP JACK |       |  |
| Comment:           |           |       |  |
| Corrective Action: |           | Date: |  |

**Equipment:**

|                    |     |       |                 |
|--------------------|-----|-------|-----------------|
| Type: Bradenhead   | # 1 |       | corrective date |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |
| Type: Pump Jack    | # 1 |       |                 |
| Comment:           |     |       |                 |
| Corrective Action: |     | Date: |                 |

**Venting:**

|        |    |  |  |
|--------|----|--|--|
| Yes/No | NO |  |  |
|--------|----|--|--|

|                    |  |       |  |
|--------------------|--|-------|--|
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |
| <b>Flaring:</b>    |  |       |  |
| Type               |  |       |  |
| Comment:           |  |       |  |
| Corrective Action: |  | Date: |  |

| Inspected Facilities |                |       |      |             |           |         |    |               |    |
|----------------------|----------------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 231527         | Type: | WELL | API Number: | 103-09198 | Status: | PR | Insp. Status: | PR |
| Producing Well       |                |       |      |             |           |         |    |               |    |
| Comment:             | Producing well |       |      |             |           |         |    |               |    |
| Corrective Action:   |                |       |      | Date:       |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Berms            |                 |                         |                       |               |                          |         |
| Compaction       |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                    | URL   |
|--------------|--------------------------------|---|
| 701102335    | Inspection 701102334 photo log | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5607858">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5607858</a> |