

Inspection Photos

API: 043-06141

Operator: JAVERNICK OIL

Inspection Date: 12/14/2021



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 043-06141 | Date: 12/14/2021

Inspection Photos



Photo 1. Drone aerial photo facing southwest toward the well site. Most of the unused equipment previously observed has been removed. There is still a pumpjack, tank, and truck that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06141 | Date: 12/14/2021

Inspection Photos



Photo 2. Drone aerial photo facing northwest toward the well site. There is a truck and tank that needs to be removed. Unused areas circled need to be recontoured and reclaimed per 1003 Rules.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06141 | Date: 12/14/2021

Inspection Photos



Photo 3. Facing southwest at the well site. The pumpjack has been disconnected from the well and needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06141 | Date: 12/14/2021

Inspection Photos



Photo 4. The buckets of oil have been removed and cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06141 | Date: 12/14/2021

Inspection Photos



Photo 5. Facing southwest toward the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06141 | Date: 12/14/2021

Inspection Photos



Photo 6. Facing southwest at the south side of the location. There is a tank and truck that needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-06141 | Date: 12/14/2021