

Inspection Photos

API: 043-40001

Operator: JAVERNICK OIL

Inspection Date: 12/14/2021



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40001 | Date: 12/14/2021

Inspection Photos



Photo 1. Facing north at the abandoned well site. The location has not been reclaimed and soils are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40001 | Date: 12/14/2021

Inspection Photos



Photo 2. There is an abandoned powerpole that remains which needs to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40001 | Date: 12/14/2021

Inspection Photos



Photo 3. There is guyline anchor cable that remains at the southeast side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40001 | Date: 12/14/2021

Inspection Photos



Photo 4. Facing southeast at the abandoned well site. The location has not been reclaimed and soils are bare of vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40001 | Date: 12/14/2021

Inspection Photos



Photo 5. There is oil stained soils at center of location that needs to be cleaned up.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40001 | Date: 12/14/2021

Inspection Photos



Photo 6. There is another guyline anchor cable that remains at the southwest side of the location.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 043-40001 | Date: 12/14/2021