

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/15/2021

Submitted Date:

12/15/2021

Document Number:

700703679**FIELD INSPECTION FORM**
 Loc ID 335423 Inspector Name: Ramsey, Scott On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
, Caerus		COGCC.inspections@caerus oilandgas.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261410	WELL	PR	06/04/2002	GW	045-07953	SHIDELER 29-11	PR
272070	WELL	PR	10/18/2004	GW	045-10012	ROBINSON 29-10 (K29NE)	PR
272071	WELL	PR	10/08/2004	GW	045-10011	COUEY 29-12 (K29NE)	PR
272912	WELL	PR	10/12/2004	GW	045-10195	ROBINSON 29-6(K29NE)	PR
282082	WELL	PR	03/25/2007	GW	045-11630	CRUZ 29-11A(K29NE)	PR
282083	WELL	PR	03/23/2007	GW	045-11629	CRUZ 29-12A(K29NE)	PR
282084	WELL	PR	03/19/2007	GW	045-11628	CRUZ 29-12C(K29NE)	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 12/15/2021 at approximately 1200, I, Inspector Scott Ramsey, conducted a routine inspection at Caerus K29NE, at Location # 335423 in Garfield county Colorado.

While there, I observed well was shut in. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (Caerus) has provided documentation of their Best Management Practices for Sediment Tracking Controls.

During this inspection the following compliance issues were observed:

1. Separator units includes 2 attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.
 2. Load lines missing bull plugs/caps.
 3. Lack of battery signage
- Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.

Location				
Lease Road:				
Type	Access			
comment:	Snow packed			
Corrective Action	L		Date:	
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	BATTERY			
Comment:	Lack of battery signage			
Corrective Action:	Comply with rule 605.e		Date:	03/02/2022
Type	OTHER			
Comment:	Separator units includes 2 attached storage tanks. The sight glass located on the side of the unit indicates the storage tank is full of an unknown fluid. No form of labeling or markers are present to identify a potential hazard or the contents of the storage tank.			
Corrective Action:	Identify all hazards associated with equipment.		Date:	03/02/2022
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	911			
Corrective Action:			Date:	
Good Housekeeping:				
Type	OTHER			
Comment:	Load lines missing bull plugs/caps.			
Corrective Action:	Comply with rule 603.i.		Date:	12/24/2021
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Equipment:				
				corrective date
Type: Pig Station	# 2			
Comment:				
Corrective Action:				Date:
Type: Vertical Heated Separator	# 7			
Comment:				

Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:			
Corrective Action:		Date:	
Type: Deadman # & Marked	# 3		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	7	300 BBLs	HEATED STEEL AST		,
Comment:	4 tanks are NOT heated				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities									
Facility ID:	261410	Type:	WELL	API Number:	045-07953	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	272070	Type:	WELL	API Number:	045-10012	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	272071	Type:	WELL	API Number:	045-10011	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	272912	Type:	WELL	API Number:	045-10195	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	282082	Type:	WELL	API Number:	045-11630	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	282083	Type:	WELL	API Number:	045-11629	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	282084	Type:	WELL	API Number:	045-11628	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:						Date:			

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
		Paving				Acces road is also acces to a residence
		Ditches				

Comment: [Limited stormwater inspection due to snow.](#)

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700703681	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5608528