

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/08/2021

Submitted Date:

12/09/2021

Document Number:

700703643

FIELD INSPECTION FORM

 Loc ID 383325 Inspector Name: Ramsey, Scott On-Site Inspection 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 10531
 Name of Operator: GRIZZLY OPERATING LLC
 Address: 5847 SAN FELIPE #3000
 City: HOUSTON State: TX Zip: 77057
Findings:

- 15 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
, TEP	970-285-9377	COGCCInspectionReports@terraep.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
301714	WELL	PR	06/15/2010	GW	045-18233	GGU MILLER 33B-31-691	PR
301715	WELL	PR	06/28/2010	GW	045-18234	GGU MILLER 33A-31-691	PR
301716	WELL	PR	06/28/2010	GW	045-18235	GGU MILLER 34B-31-691	PR
301717	WELL	PR	06/28/2010	GW	045-18236	GGU MILLER 34C-31-691	PR
301718	WELL	PR	06/28/2010	GW	045-18237	GGU MILLER 34A-31-691	PR
301719	WELL	PR	06/28/2010	GW	045-18238	GGU MILLER 34D-31-691	PR
301721	WELL	PR	06/15/2010	GW	045-18239	GGU MILLER 33C-31-691	PR

General Comment:**COGCC Inspection Report Summary**

On Wednesday 12/8/2021 at approximately 1100, I, Inspector Scott Ramsey, conducted a routine inspection at TEP Miller 6, at Location # 383325 in Garfield county Colorado.

While there, I observed normal production operations. All meters have been calibrated on location within the past year. This location is within or in close proximity to a CPW Density/High Priority Habitat, black bear, NSO habitat, Wildlife Management Area. Operator (TERRA) has provided there Piceance Basin Storm water Manual of BMP's (SC-4) for a tracking pad, there is no evidence of tracking pad at time of inspection.

During this inspection the following compliance issues were observed:

1. Some of locations BMP's are failing. See photos
2. Stored piping around well heads.
3. 2 ECD's are not connected and are stored equipment.

Refer to photograph of observed compliance issue.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	OTHER		
Comment:	Separator units include an attached storage tank. The storage tank is labeled glycol.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Type	CONTAINERS		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	911		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	STORAGE OF SUPL		
Comment:	1. Stored piping around well heads. 2. 2 ECD's are not connected and are stored equipment.		
Corrective Action:	remove all stored equipment		Date: 03/08/2022

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No _____

Comment: _____

Multiple Spills and Releases?

Equipment:			corrective date
Type: Bird Protectors	# 14		
Comment:			

Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 8		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:	See stored equipment		
Corrective Action:		Date:	
Type: Bradenhead	# 7		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 2		
Comment:	Chemical tanks in plastic containments		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	12	OTHER	HEATED STEEL AST		,
Comment:	3 tanks are NOT heated				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	625 BBLS
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
------	--	--

Comment:		
Corrective Action:	Date:	

Inspected Facilities									
Facility ID:	301714	Type:	WELL	API Number:	045-18233	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	301715	Type:	WELL	API Number:	045-18234	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	301716	Type:	WELL	API Number:	045-18235	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	301717	Type:	WELL	API Number:	045-18236	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	301718	Type:	WELL	API Number:	045-18237	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	301719	Type:	WELL	API Number:	045-18238	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				
Facility ID:	301721	Type:	WELL	API Number:	045-18239	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Producing								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Check Dams	Fail			
Ditches	Fail					
		Ditches				
Rip Rap	Fail					
		Culverts				
Berms						

Comment: [1. Some of locations BMP's are failing. See photos](#)

Corrective Action: [Install or repair required BMPs](#)

Date: 01/21/2022

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402894369	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5602645
700703647	Photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5602643