

Final Reclamation Inspection

November 16th, 2021

Operator: PDC ENERGY INC - 69175

Location ID: 322783

Inspection Document #: 701900267

NWSW Section 21 T5N R65W

Corey McDonough
Reclamation Contractor, COGCC



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

Inspection Photos
Location Name: Bragg 1
Location ID: 322783




Photo 1. 2021 aerial imagery of the well pad, tank battery and reference area (north is up).

Inspection Photos
Location Name: Bragg 1
Location ID: 322783



Photo 2. Overview photo of the reclaimed well pad taken at ground level from the southern edge looking north. Note: well pad vegetation could not be identified but appeared to be some sort of agricultural crop.

Inspection Photos
Location Name: Bragg 1
Location ID: 322783



Photo 3. Overview photo of the reclaimed tank battery taken at ground level from the southern edge looking north.

Inspection Photos
Location Name: Bragg 1
Location ID: 322783



Photo 4. Photos taken from the middle of the tank battery. Left photo facing north and right photo facing east. See photo descriptions under photo 5.

Inspection Photos
Location Name: Bragg 1
Location ID: 322783



Photo 5. Photos taken from the middle of the tank battery. Left photo facing south and right photo facing west. The photos show that the tank battery shows minimal vegetation/desirable species compared to the reference area, see photo 6.

Inspection Photos
Location Name: Bragg 1
Location ID: 322783



Photo 6. Reference area to the south of the tank battery.