



**Location**

Overall Good:

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type OTHER

Comment: Gearbox on pumping unit leaks

Corrective Action: Securely fasten all valves, pipes, fittings, and Production Facilities to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 608.e.

Date: 01/15/2022

Overall Good:

**Spills:**

Type	Area	Volume

In Containment: No

Comment:

Multiple Spills and Releases?

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
OTHER	1		BV CONCRETE		

Comment: Buried concrete vessel was removed sometime between COGCC Inspections 6/10/2021 and 10/25/2021. Rule 911.a. and Rule 913.c.(2) requires Operator to prepare and obtain the Director's approval of a Form 27 prior to Buried or partially buried vessel closure, which will be by removal. Operator is referred to Rule 913.c. in its entirety and the Rule 911.a.(4) - Oil and Gas Facility Closure Guidance Document. Contact Area EPS Rick Allison with questions.

Corrective Action: Submit a Form 27 Site Investigation and Remediation Workplan with a proposal to conduct an environmental assessment at the former buried concrete vessel location.

Date: 01/15/2022

**Paint**

Condition

Other (Content) \_\_\_\_\_

Other (Capacity) \_\_\_\_\_

Other (Type) \_\_\_\_\_

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Comment:

Corrective Action:

Date:

**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693700894	Buchner2-2H-Photos_12-8-2021	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5609727">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5609727</a>