

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/13/2021

Submitted Date:

12/13/2021

Document Number:

696303834

**FIELD INSPECTION FORM**Loc ID 428984 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

20 Number of Comments

2 Number of Corrective Actions

- ☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
428983	WELL	PR	04/01/2020	OW	123-35610	Antelope P-T-29HZ	PR
432415	WELL	PR	07/01/2021	OW	123-37098	Antelope K-O-29HNC	PR
432885	WELL	PR	01/27/2015	OW	123-37338	Antelope 41-44-29HNC	PR
438236	WELL	SI	05/01/2021	OW	123-39913	Antelope U41-Y44-29HC	SI
438244	WELL	PR	01/19/2015	OW	123-39918	Antelope P41-T44-29HNB	PR
438246	WELL	PR	01/16/2015	OW	123-39919	Antelope U41-Y44-29HNB	PR
438249	WELL	SI	07/01/2021	OW	123-39920	Antelope P41-T44-29HC	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Second Well from the West on South PAD missing Wellhead Sign; see photos		
Corrective Action:	Install sign to comply with Rule 605.d.	Date:	01/14/2022
Type	CONTAINERS		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	UNUSED EQUIPMENT		
Comment:	Unmarked Riser in SW Corner; see photo		
Corrective Action:	Comply with Rule 606	Date:	12/17/2021

Overall Good: ☐

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	LOCATION		
Comment:	Barbed Wire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panels		
Corrective Action:		Date:	

**Equipment:**

Type: Gas Meter Run	# 14		corrective date
Comment:			
Corrective Action:		Date:	

Type: Horizontal Heated Separator	# 7		
Comment:			
Corrective Action:			Date:
Type: VRT	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 4		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 7		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 7		
Comment:	Appear to be plumbed to surface		
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV CONCRETE		40.377090,-104.342500	
Comment:	Maintenance Tank					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				
				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	2	OTHER	BV CONCRETE		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)	60 BBLS	
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with the Crude Oil Tanks				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:	Shares berm with the Crude Oil Tanks				
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	12	500 BBLs	STEEL AST		40.377340,-104.343800
Comment:					
Corrective Action:					Date:
<b>Paint</b>					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
<b>Berms</b>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
<b>Venting:</b>					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
<b>Flaring:</b>					
Type					
Comment:					
Corrective Action:					Date:



Inspected Facilities				
Facility ID: 428983	Type: WELL	API Number: 123-35610	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Corrective Action:				Date:
Facility ID: 432415	Type: WELL	API Number: 123-37098	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Corrective Action:				Date:
Facility ID: 432885	Type: WELL	API Number: 123-37338	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Corrective Action:				Date:
Facility ID: 438236	Type: WELL	API Number: 123-39913	Status: SI	Insp. Status: SI
<b>Idle Well</b>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned    Reminder: _____				
Comment: SI				
Corrective Action:				Date: _____
Facility ID: 438244	Type: WELL	API Number: 123-39918	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Corrective Action:				Date:
Facility ID: 438246	Type: WELL	API Number: 123-39919	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment: PR				
Corrective Action:				Date:
Facility ID: 438249	Type: WELL	API Number: 123-39920	Status: SI	Insp. Status: SI
<b>Idle Well</b>				
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned    Reminder: _____				
Comment: SI				
Corrective Action:				Date: _____

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Routine Inspection. Second Well from the West on South PAD missing Sign. Unmarked Risers in SW Corner</a>	petrie	12/13/2021

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402897173	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5605603">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5605603</a>
696303835	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5605599">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5605599</a>