

APACHE CANYON 13-11 API# 05-071-08482 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 05, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202034



THE WATER CALLOUT AT THE ENTRANCE TO THE WELL PAD HAD FILLED IN WITH SEDIMENT PREVENTING RUN OFF TO FLOW TO THE UNDISTURBED NATURAL VEGETATION. THE CALLOUT WAS DOMINATED TO RECEIVE STORMWATER FROM THE BAR DITCH ALONG THE MAIN LEASE ROAD. THIS WILL DIRECT STORMWATER AWAY FROM THE ACCESS ROAD TO THIS LOCATION AND PREVENT THE SURFACE EROSION/RILLS.



APACHE CANYON 13-11 API# 05-071-08482 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 05, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202034



THE WATER CALLOUT AT THE ENTRANCE TO THE WELL PAD WAS DOMINATED TO RECEIVE STORMWATER FROM THE BAR DITCH ALONG THE MAIN LEASE ROAD. THIS WILL DIRECT STORMWATER AWAY FROM THE ACCESS ROAD TO THIS LOCATION AND PREVENT THE SURFACE EROSION/RILLS.



APACHE CANYON 13-11 API# 05-071-08482 – TIMBER CREEK OPERATING  
OGCC OPERATOR NUMBER 10758 - DATE: NOVEMBER 05, 2021  
CORRECTIVE ACTIONS COMPLETED REGARDING COGCC FIR DOCUMENT # 690202034



THE PIECE OF REBAR WAS REMOVED FROM THE ROADWAY. THE ROAD SURFACE WAS REGRADED AND CROWNED. THIS CONFIGURATION WILL CREATE SHEET FLOW AND ELIMINATE THE TIRE RUTS/SURFACE EROSION. THE ROAD SURFACE WAS COMPACTED BY UTILIZING A VIBRATION SOIL COMPACTION ROLLER TO PROVIDE STABILIZATION.