

FORM
INSPRev
X/20State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/15/2021

Submitted Date:

12/21/2021

Document Number:

694500379

FIELD INSPECTION FORM

 Loc ID _____ Inspector Name: NEIDEL, KRIS On-Site Inspection
 2A Doc Num: _____
Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

1 Number of Comments

0 Number of Corrective Actions

 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Operator Information:

OGCC Operator Number: 10551

Name of Operator: ANDEAVOR FIELD SERVICES LLC

Address: 539 S MAIN STREET

City: FINDLAY State: OH Zip: 45840

General Comment:

On 11/15/2021 COGCC staff, Kris Neidel inspected the Duncan b-6 Lateral spill area. WSP consulting and a representative from Marathon oil were present. WSP staff collected a soil sample at the area previously identified in the Remediation documents. COGCC inspector walked the spill path from 20 feet below the area identified as SB03 in the Remediation Project to upstream of the release point. No hydrocarbon impacts were observed. See attached photos.

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
694500380	photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5614595