

Inspection Photos  
Operator: Simcoe  
API: 067-07557  
Date: 12/17/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing with sagebrush, rubber rabbitbrush, smooth brome, and western wheatgrass.



Photo 3. View of the western project area from the southwestern corner facing northward. Berm is in place along southern edge of the project area.



Photo 4. View of reference area comprised of gambel oak shrubland, with scattered pinyon and juniper trees, sagebrush, smooth brome, and mountain mahogany.