

Inspection Photos  
Operator: Simcoe  
API: 067-08296  
Date: 12/17/2021



Photo 1. View of the project area from the well pad entrance facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Working area is fenced, outer reclamation areas are revegetating with western wheatgrass and smooth brome.



Photo 3. View of the western project area from the southwestern corner facing northward.



Photo 4. View of reference area comprised of developed neighborhood infrastructure. Park space is present east of project area.