

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

11/10/2021

Submitted Date:

12/14/2021

Document Number:

700900935**FIELD INSPECTION FORM**Loc ID 320152 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 70385Name of Operator: SMITH ENERGY CORPAddress: 12706 SHILOH RDCity: GREELEY State: CO Zip: 80631**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|--------------|----------------|-------------------------|---------------------------------|
| Smith, Glenn | (970) 381-6253 | gsmithten@what-wire.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-----------------------|-------------|
| 202829 | WELL | SI | 06/01/2018 | OW | 001-08234 | CHAMPLIN 93 AMOCO B 1 | SI |

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|--|-------|------------|
| Type | DEBRIS | | |
| Comment: | Dead Weeds throughout location. | | |
| Corrective Action: | Location is within a designated setback location, remove trash, debris and weeds per Rule 606. Corrective Action Date 12/30/2021. See attached photo # 1 through 5 | Date: | 12/30/2021 |

Overall Good: ☐**Spills:**

| | | | | |
|------|------|--------|--|--|
| Type | Area | Volume | | |
|------|------|--------|--|--|

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

| | | | |
|---------------------------------|-----|-------|-----------------|
| Type: Vertical Heated Separator | # 1 | | corrective date |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Pump Jack | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Deadman # & Marked | # 4 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |
| Type: Bradenhead | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Tanks and Berms:

| Contents | # | Capacity | Type | Tank ID | SE GPS |
|--------------------|---|----------|-----------|---------|-----------------------|
| CRUDE OIL | 1 | 300 BBLS | STEEL AST | | 39.871154,-104.225763 |
| Comment: | | | | | |
| Corrective Action: | | | | Date: | |

Paint

| | |
|-----------------|----------|
| Condition | Adequate |
| Other (Content) | |

| | | | | | | |
|---|----------|---------------------|---------------------|-------------|--------|-------|
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| <u>Berms</u> | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 1 | <50 BBLS | PBV FIBERGLASS | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| <u>Paint</u> | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| <u>Berms</u> | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 2 | <50 BBLS | CONCRETE SUMP/VAULT | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| <u>Paint</u> | | | | | | |
| Condition | Adequate | | | | | |
| Other (Content) | | | | | | |
| Other (Capacity) | | | | | | |
| Other (Type) | | | | | | |
| <u>Berms</u> | | | | | | |
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | | |
| Earth | Adequate | Walls Sufficent | Base Sufficent | Adequate | | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |
| <u>Wells Served By Facilities Above</u> | | | | | | |
| API Number | | | AirsID | | | |
| 001-08234 | | | API Number | | AirsID | |
| <u>Venting:</u> | | | | | | |
| Yes/No | NO | | | | | |

| | | | |
|--------------------|--|-------|--|
| Comment: | | | |
| Corrective Action: | | Date: | |
| Flaring: | | | |
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected FacilitiesFacility ID: 202829 Type: WELL API Number: 001-08234 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

BradenHeadDate of Last Brhd Test: _____ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: _____ Fluid Type: _____

End Surf Csg Pressure: _____

Comment: _____

Corrective Action: _____ Date: _____

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Wednesday November 10, 2021 at approximately 12:45pm. I, Inspector Chane Finkenbinder, conducted an on-site inspection at (CHAMPLIN 93 AMOCO B #1) (SMITH ENERGY), at API # 001-08234 in Adams County Colorado.</p> <p>While there, I observed a Shut in well.</p> <p>During this inspection the following possible compliance issues were observed: Dead Weeds throughout location. Location is within a designated setback location, remove trash, debris and weeds per Rule 606. Corrective Action Date 12/30/2021. See attached photo # 1 through 5</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules. This is a summary of inspection report.</p> | finkenbc | 12/14/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 700900936 | Inspection photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5615477 |