

Inspection Photos  
Operator: Simcoe  
API: 067-08870  
Date: 12/17/2021



Photo 1. View of the project area from the well pad entrance facing center.







Photo 3. View of unused materials and debris stored within the northern project area.





Photo 4. View of the eastern project area from the northeastern corner facing southward. More unused materials and debris observed here.





Photo 5. View of spotted knapweeds observed within the reclamation areas, and along the access road. Approximately 700 individuals observed (infestation).



Photo 6. View of reference area comprised riparian shrubland with sandbar willow, cottonwoods, and rubber rabbitbrush. Understory grasses are snow covered at this time.