

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/23/2021

Submitted Date:

12/23/2021

Document Number:

696303872**FIELD INSPECTION FORM**

Loc ID 429686 Inspector Name: PETRIE, ERICA On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 8960Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANYAddress: 410 17TH STREET SUITE #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☒ FOLLOW UP INSPECTION REQUIRED
☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|-------|----------------------|---------------------------------|
| , | | EHSRC@bonanzacrk.com | All Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 429687 | WELL | SI | 05/01/2021 | OW | 123-35863 | Antelope A-E-18HZ | SI |
| 429689 | WELL | SI | 06/01/2021 | OW | 123-35865 | ANTELOPE F-J-18HNB | SI |
| 431877 | WELL | SI | 04/01/2021 | OW | 123-36836 | Antelope K-O-18HNB | SI |

General Comment:

LocationOverall Good: ☒

| | | | |
|----------------------|----------------------|-------|--|
| Signs/Marker: | | | |
| Type | BATTERY | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | TANK LABELS/PLACARDS | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |
| Type | WELLHEAD | | |
| Comment: | Adequate | | |
| Corrective Action: | | Date: | |

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

| | | | |
|--------------------|-----------------------------------------------------|-------|------------|
| Type | UNUSED EQUIPMENT | | |
| Comment: | Unused Wellhead parts and Rods at Wells, see photos | | |
| Corrective Action: | Comply with Rule 606 | Date: | 02/25/2022 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

| | | | |
|--------------------|-------------|-------|--|
| Type | WELLHEAD | | |
| Comment: | Panels | | |
| Corrective Action: | | Date: | |
| Type | LOCATION | | |
| Comment: | Barbed Wire | | |
| Corrective Action: | | Date: | |

Equipment:

| | | | |
|--------------------|---------------------------------|-------|-----------------|
| | | | corrective date |
| Type: Bradenhead | # 3 | | |
| Comment: | Appear to be plumbed to surface | | |
| Corrective Action: | | Date: | |
| Type: Other | # 3 | | |
| Comment: | Wellheads | | |
| Corrective Action: | | Date: | |

| | | | |
|-----------------------------------|-----|--|-------|
| Type: Gas Meter Run | # 3 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Emission Control Device | # 4 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Horizontal Heated Separator | # 3 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |
| Type: Pump Jack | # 3 | | |
| Comment: | | | |
| Corrective Action: | | | Date: |

Tanks and Berms:

| | | | | | | |
|--------------------|---|----------|-------------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 2 | OTHER | BV CONCRETE | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | 60 BBLS | |
| Other (Type) | | |

Berms

| | | | | |
|--------------------|--------------------------------------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | Shares berm with the Crude Oil Tanks | | | |
| Corrective Action: | | | | |
| | | | | Date: |

| | | | | | | |
|--------------------|---|----------|-----------|---------|--------|-------|
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| PRODUCED WATER | 2 | 300 BBLS | STEEL AST | | , | |
| Comment: | | | | | | |
| Corrective Action: | | | | | | Date: |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | |
|----------|--------------------------------------|---------------------|---------------------|-------------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| | | | | |
| Comment: | Shares berm with the Crude Oil Tanks | | | |

| | | | | | | |
|--------------------|---|----------|-----------|---------|-----------------------|--|
| Corrective Action: | | | | | Date: | |
| Contents | # | Capacity | Type | Tank ID | SE GPS | |
| CRUDE OIL | 6 | 400 BBLs | STEEL AST | | 40.404920,-104.370370 | |
| Comment: | | | | | | |
| Corrective Action: | | | | | Date: | |

Paint

| | | |
|------------------|----------|--|
| Condition | Adequate | |
| Other (Content) | | |
| Other (Capacity) | | |
| Other (Type) | | |

Berms

| | | | | | |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance | |
| Metal | Adequate | Walls Sufficient | Base Sufficient | Adequate | |
| Comment: | | | | | |
| Corrective Action: | | | | | Date: |

Venting:

| | | | |
|--------------------|----|-------|--|
| Yes/No | NO | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 429687 Type: WELL API Number: 123-35863 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: SI

Corrective Action: _____ Date: _____

Facility ID: 429689 Type: WELL API Number: 123-35865 Status: SI Insp. Status: SI**Producing Well**Comment: SI

Corrective Action: _____ Date: _____

Facility ID: 431877 Type: WELL API Number: 123-36836 Status: SI Insp. Status: SI**Producing Well**Comment: SI

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | | Gravel | | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

| Comment | User | Date |
|------------------------------------------------------------------------|--------|------------|
| Routine Field Inspection. Unused Rods at Pumping Units | petrie | 12/23/2021 |

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| 696303873 | Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5616277 |