

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/23/2021

Submitted Date:

12/27/2021

Document Number:

701600594

FIELD INSPECTION FORM

Loc ID 302980 Inspector Name: SCHURE, KYM On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10112
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC
Address: 5057 KELLER SPRINGS RD STE 650
City: ADDISON State: TX Zip: 75001

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

10 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Eisterhold, Racheal		regulatory@foundationenergy.com	N.E. Colo. inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
252202	WELL	SI	07/01/2021	GW	125-06070	CHAPMAN 1-10	SI

General Comment:

[Routine FIR - SATISFACTORY](#)

Location

Lease Road:			
Type	Access		
comment:	Cropland with seasonal access - dryland		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:	Satisfactory		
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Satisfactory - Called No. on signage - received by Operator.		
Corrective Action:			Date: _____

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No
 Comment: NONE

Multiple Spills and Releases?

Fencing/:			
Type			
Comment:	No fencing at Wellhead		
Corrective Action:			Date:

Equipment:			
Type: Other	# 0		corrective date
Comment:	No change in equipment inventoried		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 252202 Type: WELL API Number: 125-06070 Status: SI Insp. Status: SI

Producing Well

Comment: Well returned to PR - 10/1/2021

Corrective Action:

Date:

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: UPDATE WELLFILE SHOWING SI STATUS. WELL RETURNED TO PR 10-1-21

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	In Process	Other	In Process			

Comment: [Cropland with rotational tillage](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701600630	Wellhead - Signage	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5617466