

# Inspection Photos

API: 071-06815

Operator: WAPITI OPERATING LLC

Inspection Date: 12/27/2021



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06815 | Date: 12/27/2021

## Inspection Photos



**Photo 1.** Facing north toward the access road. There is a berm and runoff ditch in this area of the road. The road has been regraded.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06815 | Date: 12/27/2021

## Inspection Photos



**Photo 2.** There are stormwater ditches carved away from the road. The disturbed loose soils are susceptible to erosion and need to be seeded and stabilized where the ditch disturbance has occurred.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06815 | Date: 12/27/2021

## Inspection Photos



**Photo 3.** A tree has fallen across the road preventing access to the well site.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 071-06815 | Date: 12/27/2021