

**FORM
INSP**

Rev
X/20

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/09/2021

Submitted Date:

12/28/2021

Document Number:

688311737

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
316997 _____ Sherman, Susan _____ 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10691
Name of Operator: PHOENIX RESOURCES LLC
Address: 5566 S SYCAMORE STREET
City: LITTLETON State: CO Zip: 80120

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

2 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Heffner, Taylor	303-219-3362	theffner@phxresources.com	Principal agent

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
234270	WELL	TA	08/01/2020	OW	121-06377	BLAKE 1	PA

General Comment:

Cut, Cap and Cover Well/Witness Cement Ends of Tank and Treater Flowlines

Gas in well when welder torch cut the wellhead, worked stopped, outside of casing was measured at 22' down and, after cutting the wellhead off on 12/10/2021, production casing was measured at 95' down. Operator will return with cementers/Bohler to bring cement to surface

Inspected FacilitiesFacility ID: 234270 Type: WELL API Number: 121-06377 Status: TA Insp. Status: PA**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688311800	Phoenix Resources Blake 1 12/9&10/2021	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5618999