

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/07/2021

Submitted Date:

12/29/2021

Document Number:

701102408

FIELD INSPECTION FORMLoc ID 316726 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10654

Name of Operator: LASSO OIL & GAS LLC

Address: 3021 RIDGE RD #156

City: ROCKWALL State: TX Zip: 75032

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

6 Number of Comments

3 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Thompson, Bud		BLThomps@BLM.gov	
Rosenberg, Kelly		kelly.rosenberg@state.co.us	
Boulger, Levin	970-509-0256	lboulger@31operating.com	
Freeman, Kris	(254) 717-0435	kfreeman@31operating.com	
, Engineering		dnr_cogccengineering@state.co.us	All engineering

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
232382	WELL	SI	09/01/2014	OW	103-60014	TRANCO 3A	TA

General Comment:

COGCC Follow Up Inspection Report Summary

Follow up to 2/26/2021 inspection # 700405583

Uncorrected action item

• Acquire MIT or plug well.

During this inspection the following compliance issues were observed:

• Storm water movement on location and access road.

• Braden inaccessible.

A follow up on this site inspection will be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.

LocationOverall Good: ☐

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911

Corrective Action: Date:

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Bradenhead	# 1		
Comment:	Braden inaccessible.		
Corrective Action:	Install appropriate fittings to allow bradenhead visual inspection as per Rule 419.a.(1), (2)		Date: 01/12/2022

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	232382	Type:	WELL	API Number:	103-60014	Status:	SI	Insp. Status:	TA
Idle Well									
Purpose: <input type="checkbox"/> Shut In <input checked="" type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: Well is not connect to a flow line. No pressure gages present. Last recorded production March 2013.									
Corrective Action: Well is not connect to a flow line. No pressure gages present. Last recorded production March 2013.									
Date: 06/30/2018									

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Fail			
		Compaction	Fail			
Compaction	Fail					

Comment: [Storm water movement on location and access road.](#)Corrective Action: [Install or repair required BMPs per Rule 1002.f.\(2\)C](#)

Date: 01/15/2022

Pits: ☐ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701102409	Inspection 701102408 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5620610