

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/22/2021

Submitted Date:

12/30/2021

Document Number:

693700905**FIELD INSPECTION FORM**Loc ID 444471 Inspector Name: ALLISON, RICK On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 96155Name of Operator: WHITING OIL & GAS CORPORATIONAddress: 1700 LINCOLN STREET SUITE 4700City: DENVER State: CO Zip: 80290**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:2 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Wheeler, Steven		steven.wheeler@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
Smith, Sydney		ssmith@fundareresources.co m	
Schlagenhauf, Mark		mark.schlagenhauf@state.co. us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
480257	SPILL OR RELEASE	AC	10/15/2021		-	Razor 25P	EI
480867	SPILL OR RELEASE	AC	10/15/2021		-	Razor 25P	EI

General Comment:

Inspected Facilities							
Facility ID:	<u>480257</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>
Facility ID:	<u>480867</u>	Type:	<u>SPILL OR</u>	API Number:	<u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EI</u>

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat)	(Long)
Oily Soil	Piles	Adequate		
Comment:	Impacted material is stockpiled on the location within bermed, lined area. Stockpile is approximately 60'x30'x6' or 400 cubic yards.			
Corrective Action:	Submit waste disposal documentaiton on Form 27 Supplemental prior to or concurrent with closure request.			Date: 01/31/2022

Spill/Remediation:

Comment:	<p>Two spills (480257&480867) are unresolved at the Razor 25P pad at the same flowline excavation, listed under Whiting Oil and Gas. Unresolved Remediation Project #20870 is open to complete the site investigation. Excavation remains open on location and confirmation soil sample results have not been received.</p> <p>Remediation of both spills has created additional impacts to vegetation east of the spill area and original location. Operator has opened new entrance to Razor 25P pad as a result of spill remediation interfering with original pad entrance.</p> <p>At least one flowline is cut/out of service and unsupported in excavation. Operator should contact Engineering Integrity Group for direction regarding repairs.</p>			
Corrective Action:	<p>Operator should submit Form 19 Supplemental for both open spills with root cause analysis on flowline failure.</p> <p>Operator should submit Form 27 Supplemental with analytical results or schedule for obtaining results.</p> <p>Operator should submit Form 27 Supplemental with reclamation plan for impacts to surface outside working pad surface.</p>			Date: 01/31/2022

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
693700906	Razor 25P Photos 12-22-2021	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5621443