

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/22/2021

Submitted Date:

12/30/2021

Document Number:

701004184**FIELD INSPECTION FORM**
 Loc ID 321817 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 61250Name of Operator: MULL DRILLING COMPANY INCAddress: 1700 N WATERFRONT PKWY B#1200City: WICHITA State: KS Zip: 67206-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
OBryhim, Reesa		ROBryhim@mulldrilling.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
208105	WELL	SI	05/01/2021	OW	017-07040	KERN FARMS A 1	PA

General Comment:[P&A Inspection](#)

Location

Lease Road:			
Type	Access		
comment:	Gravel road through farm ground		
Corrective Action	L	Date:	

Overall Good: ☒

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Overall Good: ☒

Spills:					
Type	Area	Volume			

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Ancillary equipment	# 4		
Comment:	Electric panel, cathodic rectifier, telemetry equipment, chemical tank w/containment		
Corrective Action:	Remove equipment to begin final reclamation process	Date:	01/22/2022
Type: FWKO	# 1		
Comment:			
Corrective Action:	Remove equipment to begin final reclamation process	Date:	01/22/2022
Type: Pump Jack	# 1		
Comment:	Low profile Fairfield 320		
Corrective Action:	Remove equipment to begin final reclamation process	Date:	01/22/2022

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 208105 Type: WELL API Number: 017-07040 Status: SI Insp. Status: PA**Cement**Cement ContractorContractor Name: HP Oilfield Services

Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____

Circulate to Surface: _____

Cement Fall Back: _____

Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____

Good Return During Job: _____

Production Casing

Cement Volume (sx): _____

Good Return During Job: _____

Plugging OperationsDepth Plugs(feet range): 2295/1770/621Cement Volume (sx): 200 SXSGood Return During Job: YESCement Type: CommonComment:

PEAK WIRELINE, CODELL WELL SERVICE, HALDE WATER, HP OILFIELD SERVICES. MIRU CODELL, RIH W/TBG TO 2283'. MIRU HP, PUMP 50SXS CMT DISP W/13.25BBLS. MIRU CODELL, POOH W/TBG TO 1754'. MIRU PEAK, RIH THROUGH TBG W/GUN TO 1770'. MIRU CODELL, RIH W/TBG TO 1787'. MIRU HP, PUMP 50SXS CMT DISP W/10BBL. MIRU CODELL, POOH W/TBG TO 605'. MIRU PEAK, RIH W/GUN TO 621'. MIRU HP, PUMP 100SXS W/3% CCL, DISP W/3.5BBLS. WOC FOR 1HR. MIRU CODELL, RIH W/SAND LINE AND TAG @ 300'

Corrective Action: _____

Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
701004246	location photo	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5621685