

Inspection Photos
Location Name: Roy Annala A #2
API: 05-067-08334



Roy Annala A #2 location photo.



Equipment on compressor skid is stained with white residue.

Inspection Photos
Location Name: Roy Annala A #2
API: 05-067-08334



PBV on western edge of location. ASTs have been removed since last inspection with an equipment inventory..



Reported direction of flow from Spill/Release Point ID #481340, towards the SW corner of the location.

Inspection Photos
Location Name: Roy Annala A #2
API: 05-067-08334



Produced water ran off of location into adjacent field.



Photo taken from the edge of location looking back towards point source.

Inspection Photos
Location Name: Roy Annala A #2
API: 05-067-08334



Concrete pad is stained and wet beneath prime mover.



Fluid present beneath prime mover.