

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/05/2022

Submitted Date:

01/05/2022

Document Number:

699803966

**FIELD INSPECTION FORM**

Loc ID 335200	Inspector Name: De Paolo, Corey	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	<b>Status Summary:</b> <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED  <b>Findings:</b> 23 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested  <b>ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE</b>																																																																																																															
<b>Operator Information:</b> OGCC Operator Number: 10456 Name of Operator: CAERUS PICEANCE LLC Address: 1001 17TH STREET #1600 City: DENVER State: CO Zip: 80202																																																																																																																			
<b>Contact Information:</b> <table border="1" style="width:100%; border-collapse: collapse;"> <tr> <th>Contact Name</th> <th>Phone</th> <th>Email</th> <th>Comment</th> </tr> <tr> <td>, Caerus</td> <td></td> <td>COGCC.inspections@caerus oilandgas.com</td> <td></td> </tr> </table>				Contact Name	Phone	Email	Comment	, Caerus		COGCC.inspections@caerus oilandgas.com																																																																																																									
Contact Name	Phone	Email	Comment																																																																																																																
, Caerus		COGCC.inspections@caerus oilandgas.com																																																																																																																	
<b>Inspected Facilities:</b> <table border="1" style="width:100%; border-collapse: collapse;"> <thead> <tr> <th>Facility ID</th> <th>Type</th> <th>Status</th> <th>Status Date</th> <th>Well Class</th> <th>API Num</th> <th>Facility Name</th> <th>Insp Status</th> </tr> </thead> <tbody> <tr><td>252</td><td>WELL</td><td>PR</td><td>12/01/2018</td><td>GW</td><td>045-15460</td><td>N. PARACHUTE MF02B C28 696</td><td>PR</td></tr> <tr><td>253</td><td>WELL</td><td>PR</td><td>12/01/2018</td><td>GW</td><td>045-15461</td><td>N. PARACHUTE MF01A C28 696</td><td>PR</td></tr> <tr><td>255</td><td>WELL</td><td>PR</td><td>12/01/2018</td><td>GW</td><td>045-15463</td><td>N. PARACHUTE MF01C C28 696</td><td>PR</td></tr> <tr><td>258</td><td>WELL</td><td>PR</td><td>12/01/2018</td><td>GW</td><td>045-15465</td><td>N. PARACHUTE MF02D C28 696</td><td>PR</td></tr> <tr><td>259</td><td>WELL</td><td>PR</td><td>12/01/2018</td><td>GW</td><td>045-15466</td><td>N. PARACHUTE MF01B C28 696</td><td>PR</td></tr> <tr><td>260</td><td>WELL</td><td>PR</td><td>12/01/2018</td><td>GW</td><td>045-15467</td><td>N. PARACHUTE MF02C C28 696</td><td>PR</td></tr> <tr><td>291912</td><td>WELL</td><td>PR</td><td>12/01/2018</td><td>GW</td><td>045-14553</td><td>N. PARACHUTE MF15A-21 C28 69</td><td>PR</td></tr> <tr><td>291915</td><td>WELL</td><td>PR</td><td>12/01/2018</td><td>GW</td><td>045-14552</td><td>N. PARACHUTE MF10A- 21C28 696</td><td>PR</td></tr> <tr><td>291916</td><td>WELL</td><td>PR</td><td>12/01/2018</td><td>GW</td><td>045-14551</td><td>N. PARACHUTE MF10B- 21C28 696</td><td>PR</td></tr> <tr><td>291918</td><td>WELL</td><td>PR</td><td>12/01/2018</td><td>GW</td><td>045-14550</td><td>N. PARACHUTE MF10C-21 C28 69</td><td>PR</td></tr> <tr><td>291920</td><td>WELL</td><td>PR</td><td>12/01/2018</td><td>GW</td><td>045-14549</td><td>N. PARACHUTE MF10D-21 C28 69</td><td>PR</td></tr> <tr><td>292039</td><td>WELL</td><td>PR</td><td>12/01/2018</td><td>GW</td><td>045-14554</td><td>N. PARACHUTE MF15B- 21C28696</td><td>PR</td></tr> <tr><td>293694</td><td>WELL</td><td>PR</td><td>12/01/2018</td><td>GW</td><td>045-15108</td><td>N. PARACHUTE MF15C-21 C28 69</td><td>PR</td></tr> </tbody> </table>				Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status	252	WELL	PR	12/01/2018	GW	045-15460	N. PARACHUTE MF02B C28 696	PR	253	WELL	PR	12/01/2018	GW	045-15461	N. PARACHUTE MF01A C28 696	PR	255	WELL	PR	12/01/2018	GW	045-15463	N. PARACHUTE MF01C C28 696	PR	258	WELL	PR	12/01/2018	GW	045-15465	N. PARACHUTE MF02D C28 696	PR	259	WELL	PR	12/01/2018	GW	045-15466	N. PARACHUTE MF01B C28 696	PR	260	WELL	PR	12/01/2018	GW	045-15467	N. PARACHUTE MF02C C28 696	PR	291912	WELL	PR	12/01/2018	GW	045-14553	N. PARACHUTE MF15A-21 C28 69	PR	291915	WELL	PR	12/01/2018	GW	045-14552	N. PARACHUTE MF10A- 21C28 696	PR	291916	WELL	PR	12/01/2018	GW	045-14551	N. PARACHUTE MF10B- 21C28 696	PR	291918	WELL	PR	12/01/2018	GW	045-14550	N. PARACHUTE MF10C-21 C28 69	PR	291920	WELL	PR	12/01/2018	GW	045-14549	N. PARACHUTE MF10D-21 C28 69	PR	292039	WELL	PR	12/01/2018	GW	045-14554	N. PARACHUTE MF15B- 21C28696	PR	293694	WELL	PR	12/01/2018	GW	045-15108	N. PARACHUTE MF15C-21 C28 69	PR
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status																																																																																																												
252	WELL	PR	12/01/2018	GW	045-15460	N. PARACHUTE MF02B C28 696	PR																																																																																																												
253	WELL	PR	12/01/2018	GW	045-15461	N. PARACHUTE MF01A C28 696	PR																																																																																																												
255	WELL	PR	12/01/2018	GW	045-15463	N. PARACHUTE MF01C C28 696	PR																																																																																																												
258	WELL	PR	12/01/2018	GW	045-15465	N. PARACHUTE MF02D C28 696	PR																																																																																																												
259	WELL	PR	12/01/2018	GW	045-15466	N. PARACHUTE MF01B C28 696	PR																																																																																																												
260	WELL	PR	12/01/2018	GW	045-15467	N. PARACHUTE MF02C C28 696	PR																																																																																																												
291912	WELL	PR	12/01/2018	GW	045-14553	N. PARACHUTE MF15A-21 C28 69	PR																																																																																																												
291915	WELL	PR	12/01/2018	GW	045-14552	N. PARACHUTE MF10A- 21C28 696	PR																																																																																																												
291916	WELL	PR	12/01/2018	GW	045-14551	N. PARACHUTE MF10B- 21C28 696	PR																																																																																																												
291918	WELL	PR	12/01/2018	GW	045-14550	N. PARACHUTE MF10C-21 C28 69	PR																																																																																																												
291920	WELL	PR	12/01/2018	GW	045-14549	N. PARACHUTE MF10D-21 C28 69	PR																																																																																																												
292039	WELL	PR	12/01/2018	GW	045-14554	N. PARACHUTE MF15B- 21C28696	PR																																																																																																												
293694	WELL	PR	12/01/2018	GW	045-15108	N. PARACHUTE MF15C-21 C28 69	PR																																																																																																												
<b>General Comment:</b> <div style="height: 40px;"></div>																																																																																																																			

COGCC Inspection Report Summary

On Wednesday 1/5/22 at approximately 12:00 hours, I, Inspector Corey De Paolo,  
Conducted an on-site inspection at CAERUS PICEANCE LLC N. PARACHUTE-66S96W /28NENW,  
Location #335200 in Garfield County Colorado.

While there, I observed normal production operations.

During this inspection the following compliance issues were observed:

- 1) No battery sign located at the tank battery with a corrective action date of 3/5/22.

A follow up on this site inspection needs to be conducted to ensure the  
Compliance issues have been corrected to comply with COGCC rules.

This is a summary of inspection report.

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	CONTAINERS		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	No battery sign located at the tank battery.		
Corrective Action:	A permanent, conspicuous sign will be located at the tank battery.	Date:	03/05/2022
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 911/970-285-2615

Corrective Action:

Date: \_\_\_\_\_

Overall Good: ☒

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Livestock panels		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 3		
Comment:	Chemical tanks		
Corrective Action:		Date:	
Type: Bradenhead	# 16		
Comment:	Pressure transducers located on braden head. All braden head valves are accessible.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 16		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 16		
Comment:	All wells on plunger lift		
Corrective Action:		Date:	

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities						
Facility ID:	252	Type:	WELL	API Number: 045-15460	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	253	Type:	WELL	API Number: 045-15461	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	255	Type:	WELL	API Number: 045-15463	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	258	Type:	WELL	API Number: 045-15465	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	259	Type:	WELL	API Number: 045-15466	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	260	Type:	WELL	API Number: 045-15467	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	291912	Type:	WELL	API Number: 045-14553	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:
Facility ID:	291915	Type:	WELL	API Number: 045-14552	Status: PR	Insp. Status: PR
<b>Producing Well</b>						
Comment:	Producing					
Corrective Action:						Date:

Facility ID:	291916	Type:	WELL	API Number:	045-14551	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291918	Type:	WELL	API Number:	045-14550	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	291920	Type:	WELL	API Number:	045-14549	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	292039	Type:	WELL	API Number:	045-14554	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			
Facility ID:	293694	Type:	WELL	API Number:	045-15108	Status:	PR	Insp. Status:	PR
<b><u>Producing Well</u></b>									
Comment:	Producing								
Corrective Action:						Date:			

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Sediment Traps						
		Gravel				
		Compaction				
Gravel						
		Culverts				
Ditches						
		Ditches				
		Blankets				
Compaction						
		Berms				
Berms						
				Material Handling And Spill Prevention		

Comment: [Limited storm water inspection due to location being covered with snow.](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<a href="#">Refer to Signs/Markers for corrective actions.</a>	depaoloc	01/05/2022

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699803967	Photos for Insp. #699803966	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5625977">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5625977</a>