

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/02/2021

Submitted Date:

01/06/2022

Document Number:

700900996**FIELD INSPECTION FORM**Loc ID 319995 Inspector Name: Finkenbinder, Chane On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 76859Name of Operator: SCHREIDER & COMPANY INCAddress: 9227 E LINCOLN AVE SUITE 200City: LONE TREE State: CO Zip: 80124**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name  | Phone          | Email                   | Comment |
|---------------|----------------|-------------------------|---------|
| Kelly, George | (602) 697-2484 | schneiderco@outlook.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name  | Insp Status |
|-------------|------|--------|-------------|------------|-----------|----------------|-------------|
| 202172      | WELL | SI     | 07/01/2018  | OW         | 001-07577 | ROBBINS 24-11A | SI          |

**General Comment:**

**Location**Overall Good: ☒

|                      |  |       |            |
|----------------------|--|-------|------------|
| <b>Signs/Marker:</b> |  |       |            |
| Type                 | TANK LABELS/PLACARDS   |       |            |
| Comment:             | Sign or label on tanks not posted to faded to read   |       |            |
| Corrective Action:   | Sign or label on tanks not posted to faded to read or inaccurate or sign/label too small to read at distance or installed in place where not visible. Install sign to comply with Rule 605.h. Corrective Action Date 2/4/2022. See attached photo #1 | Date: | 02/04/2022 |

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

|                    |  |       |            |
|--------------------|--|-------|------------|
| Type               | WEEDS  |       |            |
| Comment:           | Weeds and Dead Weeds throughout location   |       |            |
| Corrective Action: | Within a designated setback, remove trash, debris and weeds per Rule 606. Corrective Action Date 1/21/2022. See attached photo #1 through 3. | Date: | 01/21/2022 |

Overall Good: ☐

|                |      |        |  |  |  |
|----------------|------|--------|--|--|--|
| <b>Spills:</b> |      |        |  |  |  |
| Type           | Area | Volume |  |  |  |

In Containment: No

Comment:

☐ Multiple Spills and Releases?

|                                   |     |  |       |                 |
|-----------------------------------|-----|--|-------|-----------------|
| <b>Equipment:</b>                 |     |  |       | corrective date |
| Type: Bradenhead                  | # 1 |  |       |                 |
| Comment:                          |     |  |       |                 |
| Corrective Action:                |     |  | Date: |                 |
| Type: Deadman # & Marked          | # 4 |  |       |                 |
| Comment:                          |     |  |       |                 |
| Corrective Action:                |     |  | Date: |                 |
| Type: Pump Jack                   | # 1 |  |       |                 |
| Comment:                          |     |  |       |                 |
| Corrective Action:                |     |  | Date: |                 |
| Type: Horizontal Heated Separator | # 1 |  |       |                 |
| Comment:                          |     |  |       |                 |
| Corrective Action:                |     |  | Date: |                 |
| Type: Bird Protectors             | # 1 |  |       |                 |
| Comment:                          |     |  |       |                 |
| Corrective Action:                |     |  | Date: |                 |

**Tanks and Berms:**

|                |   |          |          |         |        |
|----------------|---|----------|----------|---------|--------|
| Contents       | # | Capacity | Type     | Tank ID | SE GPS |
| PRODUCED WATER | 1 | 100 BBLs | Open Top |         | ,      |

|                    |  |       |
|--------------------|--|-------|
| Comment:           |  |       |
| Corrective Action: |  | Date: |

Paint

|                  |  |  |
|------------------|--|--|
| Condition        |  |  |
| Other (Content)  |  |  |
| Other (Capacity) |  |  |
| Other (Type)     |  |  |

Berms

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

|                    |   |          |           |         |                       |
|--------------------|---|----------|-----------|---------|-----------------------|
| Contents           | # | Capacity | Type      | Tank ID | SE GPS                |
| CRUDE OIL          | 2 | 400 BBLs | STEEL AST |         | 39.885013,-104.293634 |
| Comment:           |   |          |           |         |                       |
| Corrective Action: |   |          |           |         | Date:                 |

Paint

|                  |          |  |
|------------------|----------|--|
| Condition        | Adequate |  |
| Other (Content)  |          |  |
| Other (Capacity) |          |  |
| Other (Type)     |          |  |

Berms

|                    |          |                     |                     |             |
|--------------------|----------|---------------------|---------------------|-------------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
| Earth              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

Wells Served By Facilities Above

|            |
|------------|
| API Number |
| 001-07577  |

AirsID

|            |        |
|------------|--------|
| API Number | AirsID |
|------------|--------|

Venting:

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

Flaring:

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

**Inspected Facilities**Facility ID: 202172 Type: WELL API Number: 001-07577 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**BradenHead**Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? No

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: Appears to be plumbed to the surface

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

| Comment  | User     | Date       |
|--|----------|------------|
| <p>COGCC Inspection Report Summary</p> <p>On Thursday December 2, 2021. at approximately 11:25am. I, Inspector Chane Finkenbinder, conducted an on-site inspection at Robbins 24-11A, Schreider &amp; Company INC, at API # 001-07577 in Adams County Colorado.</p> <p>While there, I observed a shut in well.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Weeds and Dead Weeds throughout location. Within a designated setback, remove trash, debris and weeds per Rule 606. Corrective Action Date 1/21/2022. See attached photo #1 through 3.</p> <p>Sign or label on tanks not posted to faded to read or inaccurate or sign/label too small to read at distance or installed in place where not visible. Install sign to comply with Rule 605.h. Corrective Action Date 2/4/2022. See attached photo #1</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> | finkenbc | 01/06/2022 |

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description       | URL   |
|--------------|-------------------|---|
| 700900997    | Inspection phptps | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5627238">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5627238</a> |