



**Location**

Overall Good:

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

**Spills:**

Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

**Equipment:**

Type	#				corrective date
Type: Bradenhead	# 1				
Comment:					
Corrective Action:					Date: _____
Type: Bird Protectors	# 1				
Comment:					
Corrective Action:					Date: _____
Type: Vertical Heater Treater	# 1				
Comment:					
Corrective Action:					Date: _____
Type: Pump Jack	# 1				
Comment:					
Corrective Action:					Date: _____
Type: Deadman # & Marked	# 4				
Comment:					
Corrective Action:					Date: _____

**Tanks and Birms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		39.873566,-104.268824	
Comment:						
Corrective Action:						Date: _____

**Paint**

Condition	Adequate			
Other (Content)				
Other (Capacity)				
Other (Type)				

**Birms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:	shears berms with crude				
Corrective Action:					Date:

**Wells Served By Facilities Above**

**AirsID**

API Number
001-06564
001-06007
001-06587

API Number	AirsID
------------	--------

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 201161 Type: WELL API Number: 001-06564 Status: PR Insp. Status: PR

**Producing Well**

Comment: PR

Corrective Action:

Date:

**BradenHead**

Date of Last Brhd Test: \_\_\_\_\_ Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: \_\_\_\_\_ Fluid Type: \_\_\_\_\_

End Surf Csg Pressure: \_\_\_\_\_

Comment: Appeared to be plumbed to the surface

Corrective Action:

Date:

**COGCC Comments**

Comment	User	Date
<u>Routine inspectiion</u>	finkenbc	01/07/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
700901011	Inspection photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5627738">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5627738</a>