

**FORM  
INSP**

Rev  
X/20

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

01/06/2022

Submitted Date:

01/09/2022

Document Number:

701004278

**FIELD INSPECTION FORM**

Loc ID 304526 Inspector Name: Welsh, Brian On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10112  
Name of Operator: FOUNDATION ENERGY MANAGEMENT LLC  
Address: 5057 KELLER SPRINGS RD STE 650  
City: ADDISON State: TX Zip: 75001

**Findings:**

9 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

| Contact Name  | Phone | Email                           | Comment |
|---------------|-------|---------------------------------|---------|
| Beard, Alyssa |       | regulatory@foundationenergy.com |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 264362      | WELL | PR     | 08/01/2020  | GW         | 125-08661 | CURE 13-27443 | PR          |

**General Comment:**

Routine Inspection

**Location**

|                    |                           |  |       |
|--------------------|---------------------------|--|-------|
| <b>Lease Road:</b> |                           |  |       |
| Type               | Access                    |  |       |
| comment:           | Trail through farm ground |  |       |
| Corrective Action: |                           |  | Date: |

Overall Good:

|                      |                                     |  |       |
|----------------------|-------------------------------------|--|-------|
| <b>Signs/Marker:</b> |                                     |  |       |
| Type                 | OTHER                               |  |       |
| Comment:             | Lease sign mounted to metal shed    |  |       |
| Corrective Action:   |                                     |  | Date: |
| Type                 | TANK LABELS/PLACARDS                |  |       |
| Comment:             | Metal sign by water tank            |  |       |
| Corrective Action:   |                                     |  | Date: |
| Type                 | WELLHEAD                            |  |       |
| Comment:             | Lease sign mounted to fence at unit |  |       |
| Corrective Action:   |                                     |  | Date: |

|                                  |  |  |             |
|----------------------------------|--|--|-------------|
| <b>Emergency Contact Number:</b> |  |  |             |
| Comment:                         | <input style="width: 95%;" type="text"/> |  |             |
| Corrective Action:               | <input style="width: 95%;" type="text"/> |  | Date: _____ |

Overall Good:

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment:

Multiple Spills and Releases?

|                    |                                       |  |       |
|--------------------|---------------------------------------|--|-------|
| <b>Fencing/:</b>   |                                       |  |       |
| Type               | PUMP JACK                             |  |       |
| Comment:           | Metal panels around unit and wellhead |  |       |
| Corrective Action: |                                       |  | Date: |
| Type               | SEPARATOR                             |  |       |
| Comment:           | Metal panels around metal shed        |  |       |
| Corrective Action: |                                       |  | Date: |

|                    |  |  |       |
|--------------------|--|--|-------|
| <b>Venting:</b>    |  |  |       |
| Yes/No             |  |  |       |
| Comment:           |  |  |       |
| Corrective Action: |  |  | Date: |

|                 |  |  |  |
|-----------------|--|--|--|
| <b>Flaring:</b> |  |  |  |
| Type            |  |  |  |
| Comment:        |  |  |  |

Corrective Action:

Date:

**Inspected Facilities**

Facility ID: 264362 Type: WELL API Number: 125-08661 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Producing. Casing production. Meter run is 420' W of wellhead by CR JJ](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel           | Pass            | Other                   | Pass                  |               |                          |         |

Comment: [Location and access are farmed over. Erosion leading off of location needs maintenance and BMP installed](#)

Corrective Action:

Date: \_\_\_\_\_

**Pits:**  NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description    | URL   |
|--------------|----------------|---|
| 701004290    | location photo | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5628304">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5628304</a> |