

**Inspection Photos**  
**Location Name: Fern Miller Wikstrand 2**  
**Location ID: 317738**



**Pic 1 wellhead / pump jack**



**Pic 2 wellhead. Wellhead bolts are missing on both tubing, and production casing hanger. Mechanical integrity issue are visible due to leaking wellhead on flanged connections.**