

**FORM
INSP**Rev
X/20

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

01/11/2022

Submitted Date:

01/11/2022

Document Number:

699105030

FIELD INSPECTION FORM
 Loc ID 459443 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
459439	WELL	DG	10/19/2020		123-48855	Becker D17-715	PR
459440	WELL	DG	10/18/2020		123-48856	Becker D17-735	PR
459444	WELL	XX	11/30/2018		123-48858	Becker D17-750	ND
459447	WELL	DG	10/19/2020		123-48861	Becker D17-725	PR
459449	WELL	XX	11/30/2018		123-48863	Becker D17-730	ND
459544	WELL	DG	10/18/2020		123-48934	Becker D17-745	PR

General Comment:

Snow covered ground.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	Adequate		
Corrective Action:			Date: _____

Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused Frac Tanks need to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 606		Date: 02/04/2022

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:			Date:
Type	LOCATION		
Comment:	Sound Wall South & East side		
Corrective Action:			Date:

Equipment:			corrective date
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Bradenhead	# 4		
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			

Comment:			
Corrective Action:		Date:	

Inspected FacilitiesFacility ID: 459439 Type: WELL API Number: 123-48855 Status: DG Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 05/27/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 459440 Type: WELL API Number: 123-48856 Status: DG Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHeadDate of Last Brhd Test: 05/27/2021Annual Brhd Completed? YesLast Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONEEnd Surf Csg Pressure: 0

Comment:

Corrective Action:

Date:

Facility ID: 459444 Type: WELL API Number: 123-48858 Status: XX Insp. Status: ND**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Not Drilled

Corrective Action:

Date:

Facility ID: 459447 Type: WELL API Number: 123-48861 Status: DG Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

BradenHead

Date of Last Brhd Test: 05/27/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Corrective Action: Date:

Facility ID: 459449 Type: WELL API Number: 123-48863 Status: XX Insp. Status: ND

Idle WellPurpose: ☐ Shut In ☒ Temporarily Abandoned Reminder:

Comment: Not Drilled

Corrective Action: Date:

Facility ID: 459544 Type: WELL API Number: 123-48934 Status: DG Insp. Status: PR

Producing Well

Comment: PR

Corrective Action: Date: **BradenHead**

Date of Last Brhd Test: 05/27/2021 Annual Brhd Completed? Yes

Last Brhd Test Results Initial Surf Csg Pressure: 0 Fluid Type: NONE

End Surf Csg Pressure: 0

Comment: Corrective Action: Date: **COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 1/11/22 at approximately 0856hrs, I, Inspector Adam Burns, Conducted an on-site inspection at D05-10 Pad of Noble Energy, at Location ID # 459443 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Unused Frac Tanks need to be removed for good housekeeping. Comply with Rule 606.</p> <p>With a corrective action date of 2/4/22</p> <p>See attached photos.</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p>	burnsa	01/11/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699105031	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5629839