

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/05/2022

Submitted Date:

01/11/2022

Document Number:

699602629**FIELD INSPECTION FORM**Loc ID 427188 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:16 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481373	TANK BATTERY	AC	01/06/2022		-	Ball Ranch AC15-65HN Tank Battery	IO

General Comment:

This is a TANK BATTERY inspection.
Battery: Inactive / Shut-down.

Centralized Battery serves 1 Tank Battery Facility ID
(481373).
Centralized Battery serves 1 Location ID
(427198).
(Well(s): 1: Shut-In | SI).

-Refer to Field Inspection Report doc. #699602631 and/or Location ID #427198 for Well(s) info.
Well(s): 1: Shut-In | SI.

Location

Lease Road:			
Type	Access		
comment:	Adequate		
Corrective Action		Date:	

Overall Good: ☐

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		
	Date:	<input type="text"/>	

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment: ☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Iron pipe. Surrounded by metal berms.		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Iron pipe.		
Corrective Action:		Date:	
Type	LOCATION		
Comment:	Barbed wire.		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Iron pipe.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 4		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 2		
Comment:	Crude storage vapor line combustors. Controls crude oil tanks vapors. Pilots: OFF. Inactive. Shut-down.		
Corrective Action:			Date:
Type: Ancillary equipment	# 3		
Comment:	1: ECD scrubber. 1: Solar power bank. 1: Storage shed.		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		
Comment:	1: Gas Sales Master. Calibration card indicates calibration within last year. Last calibration: 04/23/2021. Inactive, no production. 1: Gas Buyback. Calibration card indicates calibration within last year. Last calibration: 04/23/2021. Inactive.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:	Centralized Battery serves 1 Tank Battery Facility ID (481373). Centralized Battery serves 1 Location ID (427198).				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:					Date:

Paint

Condition	
-----------	--

Other (Content)	
Other (Capacity) 60 Bbls.	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms w/ crude oil tanks & produced H2O tanks.					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	500 BBLs	FIBERGLASS AST		,
Comment:					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms w/ crude oil tanks & produced H2O vault.					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	500 BBLs	STEEL AST		40.577718,-104.430295
Comment: Equalizer line connects 2 of 3 crude oil tanks.					
Corrective Action:				Date:	

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment: Shares berms w/ produced H2O tanks, vault.				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 01/05/2022 at approximately 12:30 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Facility Name: Ball Ranch AC15-65HN Tank Battery / Facility ID: 481373 Well Name(s): Ball Ranch AC 15-65HN. API: 05-123-35074. Location County: Weld County, Colorado Weather: Overcast, partial snow coverage from prior storm.</p> <p>While there, I observed: Battery: Inactive / Shut-down.</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (481373). Centralized Battery serves 1 Location ID (427198). (Well(s): 1: Shut-In SI).</p> <p>-Refer to Field Inspection Report doc. #699602631 and/or Location ID #427198 for Well(s) info. Well(s): 1: Shut-In SI.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	01/11/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699602630	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5630397