


Location Name: Becks 41-16 Location ID/API #: Spill 481394



Location Name: Becks 41-16 Location ID/API #: Spill 481394



Location Name: Becks 41-16 Location ID/API #: Spill 481394



Location Name: Becks 41-16 Location ID/API #: Spill 481394



Spill path toward culvert. Culvert shown in photo.

Location Name: Becks 41-16 Location ID/API #: Spill 481394



Location Name: Becks 41-16 Location ID/API #: Spill 481394



Location Name: Becks 41-16 Location ID/API #: Spill 481394



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Evidence of flow of produced water in drainage.

Location Name: Becks 41-16 Location ID/API #: Spill 481394



1/11/22 13:08
37.26399N 104.67153W



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Photo of vegetation in spill path.

Location Name: Becks 41-16 Location ID/API #: Spill 481394



Location Name: Becks 41-16 Location ID/API #: Spill 481394



Spill path shown on aerial photo.

Location Name: Becks 41-16 Location ID/API #: Spill 481394



Spill flowed from culvert in direction shown by arrow.

Location Name: Becks 41-16 Location ID/API #: Spill 481394



Approximate area of spill path.

Location Name: Becks 41-16 Location ID/API #: Spill 481394



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Likely area of spill terminus.

Location Name: Becks 41-16 Location ID/API #: Spill 481394

