

**FORM  
INSP**Rev  
X/20**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/11/2022

Submitted Date:

01/12/2022

Document Number:

690102790

**FIELD INSPECTION FORM**Loc ID 329585 Inspector Name: Maclaren, Joe On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL &amp; GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

3 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
		COGCCInspections@Oxy.com	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
249762	WELL	TA	08/05/2016	GW	123-17565	HOUSTON 17-8L	PA
481301	SPILL OR RELEASE	CL	12/22/2021		-	Houston 17-8L Tank Battery Release	CL

**General Comment:**COGCC Engineering Integrity Inspection; Flowline Inspection  
Photos uploaded

**Inspected Facilities**

Facility ID: 249762 Type: WELL API Number: 123-17565 Status: TA Insp. Status: PA

**Flowline**

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: \_\_\_\_\_ Size: \_\_\_\_\_ Material: \_\_\_\_\_  
 Variance: \_\_\_\_\_ Age: \_\_\_\_\_ Contents: \_\_\_\_\_

Integrity Summary

Failures: \_\_\_\_\_ Spills: \_\_\_\_\_ Repairs Made: \_\_\_\_\_  
 Coatings: \_\_\_\_\_ H2S: \_\_\_\_\_ Cathodic Protection: \_\_\_\_\_

Pressure Testing

Witnessed: \_\_\_\_\_ Test Result: \_\_\_\_\_ Charted: \_\_\_\_\_

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☐ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: Well (Houston 17-8L) has been plugged and abandoned; Cut and cap work is completed. COGCC form 42 notice of start of plugging operations doc #402791103 received 08/25/2021. COGCC form 42 notice of flowline abandonment completed notice doc #402916087 received on 01/04/2022. Wellhead flowline (OLF) is approx 330' in length; No flowline risers were observed at the (PA) wellhead or facility/ battery (decommissioned/ equipment removed) areas during this field inspection. Excavation/ remediation work (at facility) in response to the historical release is in progress.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

Facility ID: 481301 Type: SPILL OR API Number: - Status: CL Insp. Status: CL

**COGCC Comments**

Comment	User	Date
As outlined on COGCC form 19 spill report Doc #402904928 received on 12/22/2021: On December 20, 2021, a historical release of an unknown volume was discovered below the separator, produced water vessel, and dump line during decommissioning activities at the Houston 17-7L, 17-8L O SA Production Facility. Excavation and assessment activities are ongoing. The affected infrastructure has been removed and will not be replaced.	maclarej	01/12/2022

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102794	Signage	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5631004">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5631004</a>
690102795	Excavation at facility; No FL risers	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5631005">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5631005</a>
690102796	Excavation at WH; No FL risers	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5631006">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5631006</a>