



1. Spill source at the wellhead



2. Spill source: Broken valve on wellhead waterline



3. Spill path facing east from source



4. End of spill facing west toward source



5. Spill path facing west from source



6. Spill path facing south at change of direction



7. Spill path facing southeast at 2nd change of direction



8. End of spill facing northwest toward spill path

NO
OKING

COC55187

EVERGREEN

NATURAL RESOURCES LLC

BANITO FEDERAL 31-24

API 05-071-09806-0000

NW NE SECTION 24-32S-66W

WDID 1912765 / Permit # 75697-F

COC55187

EMERGENCY No. 911 or 719-846-7898 (24 Hrs)

LAT. 37.24919 / LONG. -104.73122

01.07.2022 16:39