

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE

Location ID: 335010



Photo #5643 from entrance to location.



Photo #5644 from entrance to location.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE

Location ID: 335010



Photo #5647 Storage tanks not labeled.



Photo #5648 Sight glass indicates the storage tank is full of an unknown fluid.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE

Location ID: 335010



Photo #5649 Unused equipment.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE

Location ID: 335010



Photo #5645 Location lacks stabilization.



Photo #4568 form inspection #699803450 conducted on 7/23/21.

Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC WILLIAMS-66S96W /36SWSE

Location ID: 335010



Photo #5646 Location lacks stabilization.



Photo #5650 Insufficient tracking BMP located at entrance to location.