

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE

Location ID: 335237



Photo #5659 from entrance to location.



Photo #5660 Storage tanks not labeled.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE

Location ID: 335237



**Photo #5661** Sight glass indicates that the storage tank is full of an unknown fluid.



**Photo #5662** Location lacks stabilization.

## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE

Location ID: 335237



**Photo #4264** form inspection #699803327 conducted on 6/30/21.



**Photo #5663** Location lacks stabilization.


## Inspection Photos

Location Name: TEP ROCKY MOUNTAIN LLC UNION-66S96W /33NWSE

Location ID: 335237



**Photo #4264** form inspection #699803327 conducted on 6/30/21.



**Photo #5664** Insufficient tracking BMP at entrance to location.