

Inspection Photos

API: 061-06287

Operator: CHEMCO INC

Inspection Date: 1/12/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06287
Date: 1/12/2022

Inspection Photos




Photo 1. Drone aerial photo facing down toward the well site. There is a green fiberglass tank that has blown to the fence line and across the highway shown at red arrows.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06287 Date: 1/12/2022

Inspection Photos



Photo 2. The fiberglass tank has rolled up to the fenceline and the top separated from the tank.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06287 Date: 1/12/2022

Inspection Photos



Photo 3. The top of the fiberglass tank blew across the highway.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06287 Date: 1/12/2022

Inspection Photos



Photo 4. Drone aerial photo facing southeast toward the wellsite. There are areas that are bare of vegetation which appears to be from a former spill.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06287 Date: 1/12/2022

Inspection Photos



Photo 5. Facing down toward the tank battery. The area inside of the berm needs to be kept free of vegetation. The perimeter fence around the tank needs to be installed to prevent livestock entry.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06287 Date: 1/12/2022

Inspection Photos



Photo 6. Facing toward the pumpjack.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06287 Date: 1/12/2022