

Inspection Photos

API: 061-05138

Operator: WESTERN OPERATING COMPANY

Inspection Date: 1/12/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-05138 | Date: 1/12/2022

Inspection Photos



Photo 1. Facing east at the beginning of the access road. The two track road remains with compacted soils. The access road needs to be recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 1/12/2022

Inspection Photos



Photo 2. Facing north along the access road which has not been recontoured and reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 1/12/2022

Inspection Photos



Photo 3. Facing northwest toward the former tank battery site located 300' southwest of the well site. This area has not been reclaimed. An electric fence was installed around this area which is already in disrepair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 1/12/2022

Inspection Photos



Photo 4. There is a pipe riser that remains at the battery site. All abandoned risers need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 1/12/2022

Inspection Photos



Photo 5. There are two pipes that remain at the battery site that need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 1/12/2022

Inspection Photos



Photo 6. Facing southwest toward the abandoned battery site. This area has not been reclaimed. An electric fence was installed around this area which is already in disrepair.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 1/12/2022

Inspection Photos



Photo 7. There are additional abandoned risers that remain at the tank battery site. All abandoned risers need to be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 1/12/2022

Inspection Photos




Photo 8. Facing northeast toward the abandoned well site. This area has not been reclaimed. Bare soils that are not stabilized and are susceptible to further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 1/12/2022

Inspection Photos



Photo 9. Facing south toward the abandoned well site. This area has not been reclaimed. Bare soils that are not stabilized and are susceptible to further erosion.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 1/12/2022

Inspection Photos



Photo 10. Drone aerial photo facing north along the access road toward the location. The red arrow points to the former tank battery site and yellow arrow points to the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 1/12/2022

Inspection Photos



Photo 11. Facing northeast toward the tank battery site and well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 1/12/2022

Inspection Photos



Photo 12. Facing back south toward the well site. The red arrow points to the former tank battery site and yellow arrow points to the well site.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-05138 | Date: 1/12/2022