

Inspection Photos

API: 061-06041

Operator: WESTERN OPERATING COMPANY

Inspection Date: 1/12/2022



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06041 - Date: 1/12/2022

Inspection Photos



Photo 1. Facing west at the beginning of the access road which consists of undesirable weeds. The cattle guard has not been removed and the road is not reclaimed in this area.



COLORADO

**Oil & Gas Conservation
Commission**

Department of Natural Resources

API: 061-06041 - Date: 1/12/2022

Inspection Photos



Photo 2. Facing back east toward the cattleguard and access road. The cattleguard must be removed and the access road reclaimed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 1/12/2022

Inspection Photos



Photo 3. The powerline used for operating the well dead ends at the location and the entire unused portion of the powerline must be removed.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 1/12/2022

Inspection Photos



Photo 4. North side of the location facing south. This area of the location is approximately 120'x120' and consist of only undesirable weeds.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 1/12/2022

Inspection Photos



Photo 5. View of groundcover consisting of undesirable weeds (*Kochia* sp.) and no desirable vegetation.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 1/12/2022

Inspection Photos



Photo 6. Facing north toward the surrounding undisturbed area which consists of a uniform native vegetation cover.



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

API: 061-06041 - Date: 1/12/2022