

**FORM
INSP**Rev
X/20**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/12/2022

Submitted Date:

01/14/2022

Document Number:

699602638

FIELD INSPECTION FORMLoc ID 429643 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 100322

Name of Operator: NOBLE ENERGY INC

Address: 1001 NOBLE ENERGY WAY

City: HOUSTON State: TX Zip: 77070

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

16 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		rbucogccinspectionreports@c hevron.onmicrosoft.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
481387	TANK BATTERY	AC	01/10/2022		-	Bethyl GW 30-09 Tank Battery	IO

General Comment:

This is a TANK BATTERY inspection.
Battery: Inactive / Shut-down.

Centralized Battery serves 1 Tank Battery Facility ID
(481387).
Centralized Battery serves 1 Location ID
(429642).
(Well(s): 1: Shut-In | SI).

-Refer to Field Inspection Report doc. #699602640 and/or Location ID #429642 for Well(s) info.
Well(s): 1: Shut-In | SI.

Location				
Lease Road:				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	CONTAINERS			
Comment:	Propane.			
Corrective Action:				Date:
Type	BATTERY			
Comment:				
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	LOCATION			
Comment:	Barbed wire.			
Corrective Action:				Date:
Type	SEPARATOR			
Comment:	Separator: Surrounded by earth berms. Traeters: Surrounded by metal berms.			
Corrective Action:				Date:
Type	OTHER			
Comment:	Propane tank: Iron panel.			
Corrective Action:				Date:
Equipment:				
Type: Bird Protectors	# 4			corrective date
Comment:				
Corrective Action:				Date:

Type: Ancillary equipment	# 2		
Comment: 1: Propane tank. Placards. 1: ECD scrubber.			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 1		
Comment: Crude storage vapor line combustor. Controls crude oil tanks vapors. Pilots: OFF. Inactive / Shut-down.			
Corrective Action:		Date:	
Type: Vertical Heater Treater	# 2		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		,
Comment:		Centralized Battery serves 1 Tank Battery Facility ID (481387). Centralized Battery serves 1 Location ID (429642).			
Corrective Action:				Date:	

Paint

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:			Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	CONCRETE SUMP/VAULT		,
Comment:					
Corrective Action:			Date:		

Paint

Condition	
Other (Content)	
Other (Capacity)	60 Bbls.
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance

Inspector Name: Evins, Bret

Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms w/ crude oil tanks & produced H2O tanks.					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	4	500 BBLs	FIBERGLASS AST		,
Comment: Insulated. Equalizer lines connect 3 of 4 produced H2O tanks.					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms w/ crude oil tanks & produced H2O vault.					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	10	500 BBLs	STEEL AST		40.628580,-104.468690
Comment: Equalizer lines connect crude oil tanks.					
Corrective Action:					Date:
Paint					
Condition	Adequate				
Other (Content)					
Other (Capacity)					
Other (Type)					
Berms					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment: Shares berms w/ produced H2O tanks, vault.					
Corrective Action:					Date:
Venting:					
Yes/No	NO				
Comment:					
Corrective Action:					Date:
Flaring:					
Type					
Comment:					
Corrective Action:					Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary:</p> <p>On WED 01/12/2022 at approximately 15:34 hrs. I, Bret Evins, conducted an on-site inspection at: Operator Name: NOBLE ENERGY INC Facility Name: Bethyl GW 30-09 Tank Battery / Facility ID: 481387 Well Name(s): Bethyl GW30-16. API: 05-123-35855. Location County: Weld County, Colorado Weather: Mostly Sunny, partial snow coverage from prior storm.</p> <p>While there, I observed: Battery: Inactive / Shut-down.</p> <p>Centralized Battery serves 1 Tank Battery Facility ID (481387). Centralized Battery serves 1 Location ID (429642). (Well(s): 1: Shut-In SI).</p> <p>-Refer to Field Inspection Report doc. #699602640 and/or Location ID #429642 for Well(s) info. Well(s): 1: Shut-In SI.</p> <p>During this inspection, NO possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	01/14/2022

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699602639	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5633918