

**Inspection Photos**  
**Location Name: Firecracker Consolidation**  
**Spill ID: 481413**



**Photo 1 – Spill area. Fencing present around open excavation.**



**Photo 2 – Excavation. Impacts remain visible in-situ.**



**Inspection Photos**  
**Location Name: Firecracker Consolidation**  
**Spill ID: 481413**



**Photo 3 – Excavation. Location of observed leak.**



**Photo 4 – Spill excavation. Impacts remain in-situ.**