

FORM  
INSPRev  
X/20State of Colorado  
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

01/13/2022

Submitted Date:

01/14/2022

Document Number:

690102805

## FIELD INSPECTION FORM

 Loc ID 336259 Inspector Name: Maclaren, Joe On-Site Inspection  2A Doc Num:
**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**
 OGCC Operator Number: 47120  
 Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP  
 Address: P O BOX 173779  
 City: DENVER State: CO Zip: 80217-
**Findings:**
 2 Number of Comments  
 0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
 PREVIOUS INSPECTIONS THAT HAVE NOT  
 BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		COGCCInspections@Oxy.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265038	WELL	PR	11/01/2021	GW	123-21148	FT VASQUEZ 8-36A	EG
294740	WELL	PR	11/01/2021	GW	123-25542	FORT 41-36	EG
296106	WELL	SI	04/01/2020	OW	123-25891	FORT 37-25	PA
445411	LOCATION	AC			-	FT VASQUEZ 1&8-36A O SA 34002657	EG

**General Comment:**

COGCC Engineering Integrity Inspection; Flowline Inspection  
 Photos uploaded

**Inspected Facilities**

Facility ID: <u>265038</u>	Type: <u>WELL</u>	API Number: <u>123-21148</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>294740</u>	Type: <u>WELL</u>	API Number: <u>123-25542</u>	Status: <u>PR</u>	Insp. Status: <u>EG</u>
Facility ID: <u>296106</u>	Type: <u>WELL</u>	API Number: <u>123-25891</u>	Status: <u>SI</u>	Insp. Status: <u>PA</u>

**Flowline**

#1	Type: Non-Well Site	of Lines
----	---------------------	----------

Flowline Description

Flowline Type: Non-Well Site      Size:      Material:  
 Variance:      Age:      Contents:

Integrity Summary

Failures:      Spills:      Repairs Made:  
 Coatings:      H2S:      Cathodic Protection:

Pressure Testing

Witnessed:      Test Result:      Charted:

COGCC Rules(check all that apply)

1101. Installation and Reclamation     1102. Operations, Maintenance, and Repair     1103. Abandonment

Comment: Well (Fort 37-25) is plugged and abandoned; Cut and cap work is completed. COGCC form 42 notice of start of plugging operations doc #402804416 received 09/08/2021. COGCC form 42 notice of flowline abandonment completed doc #02887558 received on 12/06/2021. Wellhead flowline (OLF) is approx 450' in length; No flowlines/ risers were observed in the open excavation at the (PA) wellhead during this field inspection. (2) inactive flowline risers (isolated/ bullplugged) were observed at manifold inlet to HHS. The facility/ battery services (2) additional wells; facility and wells are currently SI. Work on location is in progress. Note: Inactive flowline risers need to be labeled; flowline abandonment/ removal completed.

Corrective Action:

Date:

Facility ID: <u>445411</u>	Type: <u>LOCATION</u>	API Number: <u>-</u>	Status: <u>AC</u>	Insp. Status: <u>EG</u>
----------------------------	-----------------------	----------------------	-------------------	-------------------------

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690102810	Fort 37-25 (PA) well and signage	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5634172">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5634172</a>
690102811	Flowline manifold at inlet to HHS	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5634173">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5634173</a>