

Inspection Photos
Operator: Catamount
API: 067-09914
Date: 1/11/2022



Photo 1. View of project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southeastern corner facing westward. Revegetation is progressing in portions of the interim reclamation area, but remain sparse/bare on the southern berm, down-slope from the eastern berm, and on the cut-slopes.



Photo 3. View of the eastern project area from the southeastern corner facing northward.



Photo 4. View of eastern berms and area down-slope from berms where little desirable vegetation is present, bare soils are not stabilized.



Photo 5. View of reference area, comprised of irrigated grass field with thickspike wheatgrass, smooth brome, willows, and rabbitbrush.