

Inspection Photos  
Operator: Simcoe  
API: 007-06326  
Date: 1/11/2022



Photo 1. View of project area from the well pad entrance facing center.





Photo 2. View of the western fill slope from the southwestern corner facing northward. Revegetation appears to be progressing, largely in a grazed vegetative condition at this time.





Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of trailers and car stored within the northwestern project area. This portion of the project area needs interim reclamation if not needed for production operations.





Photo 5. View of reference area, comprised of apple trees and irrigated grasses, in a grazed vegetative condition.