

Inspection Photos  
Operator: Simcoe  
API: 007-06221  
Date: 1/11/2022



Photo 1. View of project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation appears to be progressing, largely in a grazed vegetative condition at this time, needs to be assessed during the active growing season.



Photo 3. View of the eastern project area from the southeastern project area from the southeastern corner facing northward.



Photo 4. View of reference area, comprised of irrigated and non-irrigated grass field with scattered pinyon and juniper trees, western wheatgrass and blue grama observed in the understory.