

Inspection Photos
Operator: Simcoe
API: 007-06149
Date: 1/11/2022



Photo 1. View of project area from the southeastern corner facing center.



Photo 2. View of the southern fill slope from the southeastern corner facing westward. Revegetation appears to be progressing, largely in a grazed vegetative condition at this time, needs to be assessed during the active growing season. Western wheatgrass and blue grama are observable.



Photo 3. View of the western project area from the northwestern corner facing southward.



Photo 4. View of reference area, comprised of irrigated and non-irrigated grass field with scattered pinyon and juniper trees, western wheatgrass and blue grama observed in the understory.