

Inspection Photos
Operator: Simcoe
API: 007-06086
Date: 1/11/2022



Photo 1. View of project area from the well pad entrance facing center.



Photo 2. View of the western fill slope from the southwestern corner facing northward. Revegetation appears to be progressing with blue grama, rubber rabbitbrush, western wheatgrass, and crested wheatgrass.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of reference area, comprised of irrigated and non-irrigated grass field with scattered pinyon and juniper trees, western wheatgrass and blue grama observed in the understory.